


# Smoke and Dye Testing Summary

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-215	Smoke	8/10/2009	ADS/TM	S19KK_053MH	Dry	Yes	563.38



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-215	Smoke	8/10/2009	ADS/TM	S19KK_053MH	Dry	Yes	563.38

### Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S19KK_053G1	S19KK_053MH	S19KK_066MH	168.814	8
S19KK_057G1	S19KK_057DE	S19KK_053MH	58.0375	8
S19KK_041G1	S19KK_041MH	S19KK_053MH	336.525	8

### Observations & Photos

**Obs\_ID** S1028-215-OB01  
**Address** 1904 Walbrook Ave  
**Status** Private  
**Source** Cleanout

**Location** Yard - back  
**Nearest MH** S19KK\_053MH

**Comments** Smoke from cleanout in back yard. 1904 Walbrook Ave.



**Picture** \S1028-215-OB01-P01.jpg

**Comments** Back of house, 1904 Walbrook Ave.

**Obs\_ID** S1028-215-OB02  
**Address** 1924 Walbrook Ave  
**Status** Private  
**Source** Cleanout

**Location** Yard - back  
**Nearest MH** S19KK\_053MH

**Comments** Smoke from cleanout in back yard. 1924 Walbrook Ave.



**Picture** \S1028-215-OB02-P01.jpg

**Comments** Back of house, 1924 Walbrook Ave.

---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-215	Smoke	8/10/2009	ADS/TM	S19KK_053MH	Dry	Yes	563.38

**Obs\_ID** S1028-215-OB03

**Address** 1933 Ridgehill Ave

**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S19KK\_041MH

**Comments** Smoke from above-grade cleanout in back yard. 1933 Ridgehill Ave.



**Picture** \S1028-215-OB03-P01.jpg

**Comments** Back of house, 1933 Ridgehill Ave.

**Obs\_ID** S1028-215-OB04

**Address** 1945 Ridgehill Ave

**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S19KK\_041MH

**Comments** Smoke from cleanout in back yard. 1945 Ridgehill Ave.



**Picture** \S1028-215-OB04-P01.jpg

**Comments** Back of house, 1945 Ridgehill Ave.

**Obs\_ID** S1028-215-OB05

**Address** 1942 Walbrook Ave


**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S19KK\_041MH

**Comments** Smoke from cleanout in back yard. 1942 Ridgehill Ave.



**Picture** \S1028-215-OB05-P01.jpg

**Comments** Back of house, 1942 Ridgehill Ave.

